



Potential Responsible Party

Name/Business	Holland America
Vessel Name	Zaandam
Mailing Address	Unknown
Contact Name	Unknown
Contact Number	Unknown
Is PRP Vessel Aware of Incidents	Don't know
Will Vessel Be Self Reporting Incident to ADEC-SPAR	Don't know

Reporting Party Information

Report Date	Jun 9, 2018
Person Reporting	Thomas Guiney, Ocean Ranger
Vessel Stationed Aboard	Holland Zaandam
Vessel Code	HZA
Trip Type	VO

Spill Information

Date & Time of Spill	Jun 9, 2018 12:35:00 PM AKDT
Date & Time Discovered	Jun 9, 2018 12:35:00 PM AKDT
Description of Location	Icy Strait Point. At the dock.
Latitude	58 degrees 08.01 minutes N.
Longitude	135 degrees 27.98 minutes W.
Substance Type	UNK - Unknown
Product Spilled	Scrubber washwater
Spilled Quantity	Unknown
Spilled UOM	Cups
Affected Area (number)	20
Affected UOM	Sq Meters
Color And Appearance	Rainbow
Source of Spill	Scrubber wash water.
Is it a greater than 400GT Vessel?	Yes
Cause of Spill	Discharge wash water from the operation of the Exhaust Gas Cleaning System.
Cleanup Actions	None.
Comments	The vessel operates an 'open' Exhaust Gas Cleaning System. A condition of the operating system is a sheen like substance on the water surface at the discharge wash water point from the vessel on the starboard side.

Photos



Photo 1 Comments

Discharge wash water from the scrubber with apparent sheen.

Photo 2



Photo 2 Comments

Discharge wash water from the scrubber system with apparent sheen.