

**Potential Responsible Party**

Name/Business	Holland America Cruise
Vessel Name	Nieuw Amsterdam
Mailing Address	Seattle, Washington
Contact Name	Holland America Cruise Line
Contact Number	Unknown
Is PRP Vessel Aware of Incidents	Yes
Remarks	Informed EO about discoloration of foam observed on port aft outboard of lifeboat station 18.
Will Vessel Be Self Reporting Incident to ADEC-SPAR	Don't know
Remarks	EO observed discoloration of foam in area of EGCS "open loop" overboard discharge.

Reporting Party Information

Report Date	May 31, 2018
Person Reporting	Mark Farley - Ocean Ranger
Vessel Stationed Aboard	HNI
Trip Type	VO

Spill Information

Date & Time of Spill	May 31, 2018 5:30:00 PM AKDT
Date & Time Discovered	May 31, 2018 5:30:00 PM AKDT
Description of Location	Berth number three in the Port of Ketchikan.
Latitude	55 20' 38.18"N
Longitude	131 39' 6.27" W
Substance Type	UNK - Unknown
Product Spilled	Unknown
Spilled Quantity	Unknown
Spilled UOM	Unknown
Affected Area (number)	100
Affected UOM	Sq Feet
Color And Appearance	Unknown
Source of Spill	Discoloration of foam (yellowish brown) observed in area of EGCS "open loop" overboard discharge from DG number one.
Is it a greater than 400GT Vessel?	Yes
Cause of Spill	Discoloration of foam (yellowish brown) observed in area of EGCS "open loop" overboard discharge from DG number one.
Cleanup Actions	None.

Photos

Photo 1




Photo 1 Comments

053118 @ 1730 Photo taken from deck number three port outboard of lifeboat number 18. Discoloration of foam in area of DG number one EGCS "open loop" overboard discharge.

Photo 2




Photo 2 Comments

053118 @ 1734 Photo taken from deck number ten port midship. Discoloration of foam in area of DG number one EGCS "open loop" overboard discharge.