



Potential Responsible Party

Name/Business	Princess Cruise Line
Vessel Name	Golden Princess
Mailing Address	Princess Cruise Line
Contact Name	Princess Cruise Line
Contact Number	Unknown
Is PRP Vessel Aware of Incidents	Yes
Remarks	Informed EO about discoloration around EGCS "open loop" overboard discharge from DG number two while maneuvering to the Franklin Dock in the Port of Juneau.
Will Vessel Be Self Reporting Incident to ADEC-SPAR	Don't know
Remarks	Informed EO about discoloration around EGCS "open loop" overboard discharge from DG number two while maneuvering to the Franklin Dock in the Port of Juneau.

Reporting Party Information

Report Date	Jun 13, 2018
Person Reporting	Ocean Ranger Mark Farley
Vessel Stationed Aboard	Princess Golden
Vessel Code	PGL
Trip Type	VO

Spill Information

Date & Time of Spill	Jun 13, 2018 6:05:00 AM AKDT
Date & Time Discovered	Jun 13, 2018 6:05:00 AM AKDT
Description of Location	Port of Juneau, Golden Princess was maneuvering to the Franklin Dock. Golden Princess docked port side to the aFranklin Dock, DG number two EGCS "open loop" overboard discharge is below waterline on starboard side aft (between lifeboat/tender station 21 and 23.
Latitude	58 17.50" N
Longitude	134 23.73" W
Substance Type	PW - Process Water
Product Spilled	Unknown
Spilled Quantity	Unknown
Spilled UOM	Unknown
Affected Area (number)	50
Affected UOM	Sq Meters
Color And Appearance	Silver/Gray

Princess Golden Hazardous Spill
Notification
Source of Spill

2018-06-13

Reference # - HS-20180613-1880601867

Is it a greater than 400GT Vessel?

Cause of Spill

Cleanup Actions

Observed discoloration in area of EGCS
"open loop" overboard discharge from DG
number two.

No

Observed discoloration in area of EGCS
"open loop" overboard discharge from DG
number two.

None observed, tide seen taking discoloration
away from vessel. EGCS "open loop"
overboard discharge for DG number two
secured at after PGL was docked at the
Franklin Dock and finished with engines.

Photos

Photo 1



Photo 1 Comments

061318 @ 0605 Discoloration in area of
EGCS "open loop" overboard discharge from
DG number two. (Photo taken from deck
seven - Promenade Deck starboard aft
between lifeboat/tender stations twenty one
and twenty three)

Photo 2



Photo 2 Comments

061318 @ 0607 Discoloration in area of
EGCS "open loop" overboard discharge from
DG number two. (Photo taken from deck
seven - Promenade Deck starboard aft
between lifeboat/tender stations twenty one
and twenty three)

Photo 3 Comments



061318 @ 0613 Discoloration in area of EGCS "open loop" overboard discharge from DG number two. (Photo taken from deck seven - Promenade Deck starboard aft between lifeboat/tender stations twenty one and twenty three)

Photo 4



Photo 4 Comments

061318 @ 0615 Discoloration in area of EGCS "open loop" overboard discharge from DG number two. (Photo taken from deck seven - Promenade Deck starboard aft between lifeboat/tender stations twenty one and twenty three)