

**Potential Responsible Party**

---

Vessel Name	Ruby Princess
Is PRP Vessel Aware of Incidents	Yes
Remarks	Was brought to Officer on watch attention by onboard Ocean Ranger
Will Vessel Be Self Reporting Incident to ADEC-SPAR	Don't know

**Reporting Party Information**

---

Report Date	Aug 23, 2018
Person Reporting	James Ham
Vessel Stationed Aboard	Princess Ruby
Vessel Code	PRU
Trip Type	VO

**Spill Information**

---

Date & Time of Spill	Aug 23, 2018 7:00:00 AM AKDT
Date & Time Discovered	Aug 23, 2018 10:52:00 AM AKDT
Description of Location	KTN. Berth 4
Substance Type	UNK - Unknown
Spilled UOM	Unknown
Affected UOM	Unknown
Color And Appearance	Dark/True
Source of Spill	Scrubber system discharge waste water
Is it a greater than 400GT Vessel?	Yes
Cause of Spill	Vessel was back flushing exhaust gas scrubber system discharge filter when incident happened.
Comments	While making observations on open deck on port side @ 0715 I observed what looked like black soot floating on top of water coming from exhaust gas scrubber discharge port. I immediately took pictures of soot and discoloration floating on top of water and then contacted Environmental Officer. Environmental Officer met me on deck right away and evaluated the situation and contacted Engine Room. Engine immediately stopped Scrubber system operation . Switchover was completed @ 0750.

**Photos**

---




Photo 1 Comments

Picture from Scrubber System Discharge port  
@0715 8/23/18

Photo 2



Photo 2 Comments

Soot from Scrubber System discharge port @  
0715 8/23/18

Photo 3



Photo 3 Comments

Discoloration from Scrubber discharge port  
@ 0715 8/23/18

Photo 4



Princess Ruby Hazardous Spill Notification  
Photo 4 Comments

2018-08-23

Reference # - HS-20180823-1885884827  
Discoloration from Scrubber discharge port  
@ 0715 8/23/18